
# 9 Exploded view FK 15.1

052-61001 · R 25 × 75

Schematic parts identification. Blue part numbers open the shop.




## 10 Spare parts

| Item | Qty. | Description | Part number |
|---|---|---|---|
| 1 | 1 | Chisel bushing R 25 × 75 | 052-7762 |
| 2 | 1 | Cylinder | 052-2700 |
| 3 | 1 | Piston | 052-1902 |
| 4 | 1 | Valve housing | 052-2703 |
| 5 | 1 | Valve sleeve | 052-1904 |
| 6 | 1 | Complete buffer | 052-2707 |
| 7 | 1 | Pin | 304-3632 |
| 8 | 1 | Complete handle | 052-2701 |
| 9 | 1 | Ring | 307-2527 |
| 10 | 1 | Clamping nut | 052-2704 |
| 11 | 1 | Complete screw cap | 052-1925 |
| 12 | 1 | Impact ring | 307-2043 |
| 13 | 1 | Pin | 304-3422 |
| 14 | 1 | Ball | 307-2088 |
| 15 | 1 | Compression spring | 304-7535 |
| 16 | 1 | Retaining ring | 304-7165 |
| 17 | 1 | Nipple | 306-0228 |
| 18 | 1 | Valve | 052-8322 |
| 19 | 1 | Trigger | 052-8397 |
| 20 | 2 | Cylindrical pin | 304-3444 |
| 21 | 1 | O-ring | 307-2451 |
| 22 | 1 | Sealing ring | 313-531775 |

**NOTICE – Damage to the cylinder**
Have chisel bushings replaced only by F+K Service. Incorrect removal or replacement can damage the cylinder. Do not remove or replace them yourself.


**NOTICE – Damage to the hammer**
When replacing the valve sleeve or valve housing, reusing the buffer can damage the hammer. Always replace the complete buffer 052-2707 as well.

**Variants and spare-parts orders**
FK 15.1: R 25 × 75; complete screw cap 052-1925. Handle (8) is also available complete (052-2701). Two handle pins 304-3444.

# 9 Exploded view FK 15.2

052-61002 · S 22 × 82,5

Schematic parts identification. Blue part numbers open the shop.




## 10 Spare parts

| Item | Qty. | Description | Part number |
|---|---|---|---|
| 1 | 1 | Chisel bushing S 22 × 82,5 | 052-2849 |
| 2 | 1 | Cylinder | 052-2700 |
| 3 | 1 | Piston | 052-1902 |
| 4 | 1 | Valve housing | 052-2703 |
| 5 | 1 | Valve sleeve | 052-1904 |
| 6 | 1 | Complete buffer | 052-2707 |
| 7 | 1 | Pin | 304-3632 |
| 8 | 1 | Complete handle | 052-2701 |
| 9 | 1 | Ring | 307-2527 |
| 10 | 1 | Clamping nut | 052-2704 |
| 11 | 1 | Complete retaining cap | 052-2520 |
| 12 | 1 | Retaining lever | 052-2846 |
| 13 | 1 | Pin | 304-3422 |
| 14 | 1 | Ball | 307-2088 |
| 15 | 1 | Compression spring | 304-7535 |
| 16 | 1 | Retaining ring | 304-7165 |
| 17 | 1 | Nipple | 306-0228 |
| 18 | 1 | Valve | 052-8322 |
| 19 | 1 | Trigger | 052-8397 |
| 20 | 2 | Cylindrical pin | 304-3444 |
| 21 | 1 | O-ring | 307-2451 |
| 22 | 1 | Spring pin | 304-3654 |
| 23 | 1 | Spring pin | 304-3653 |
| 24 | 1 | Push pin | 052-8115 |
| 25 | 1 | Compression spring | 304-7501 |
| 26 | 1 | Screw | 308-100105 |
| 27 | 1 | Nut | 308-110020 |
| 28 | 1 | Sealing ring | 313-531775 |

**NOTICE – Damage to the cylinder**
Have chisel bushings replaced only by F+K Service. Incorrect removal or replacement can damage the cylinder. Do not remove or replace them yourself.


**NOTICE – Damage to the hammer**
When replacing the valve sleeve or valve housing, reusing the buffer can damage the hammer. Always replace the complete buffer 052-2707 as well.

**Variants and spare-parts orders**
FK 15.2: S 22 × 82.5; bushing 052-2849; complete retaining cap 052-2520. Handle (8) is also available complete (052-2701). Two handle pins 304-3444.

# 9 Exploded view FK 15.4

052-61004 · R 25 × 75

Schematic parts identification. Blue part numbers open the shop.




## 10 Spare parts

| Item | Qty. | Description | Part number |
|---|---|---|---|
| 1 | 1 | Chisel bushing R 25 × 75 | 052-7762 |
| 2 | 1 | Cylinder | 052-2700 |
| 3 | 1 | Piston | 052-1902 |
| 4 | 1 | Valve housing | 052-2703 |
| 5 | 1 | Valve sleeve | 052-1904 |
| 6 | 1 | Complete buffer | 052-2707 |
| 7 | 1 | Pin | 304-3632 |
| 8 | 1 | Complete handle | 052-2701 |
| 9 | 1 | Ring | 307-2527 |
| 10 | 1 | Clamping nut | 052-2704 |
| 11 | 1 | Complete retaining cap | 052-2520 |
| 12 | 1 | Retaining lever | 052-2846 |
| 13 | 1 | Pin | 304-3422 |
| 14 | 1 | Ball | 307-2088 |
| 15 | 1 | Compression spring | 304-7535 |
| 16 | 1 | Retaining ring | 304-7165 |
| 17 | 1 | Nipple | 306-0228 |
| 18 | 1 | Valve | 052-8322 |
| 19 | 1 | Trigger | 052-8397 |
| 20 | 2 | Cylindrical pin | 304-3444 |
| 21 | 1 | O-ring | 307-2451 |
| 22 | 1 | Spring pin | 304-3654 |
| 23 | 1 | Spring pin | 304-3653 |
| 24 | 1 | Push pin | 052-8115 |
| 25 | 1 | Compression spring | 304-7501 |
| 26 | 1 | Screw | 308-100105 |
| 27 | 1 | Nut | 308-110020 |
| 28 | 1 | Sealing ring | 313-531775 |

**NOTICE – Damage to the cylinder**
Have chisel bushings replaced only by F+K Service. Incorrect removal or replacement can damage the cylinder. Do not remove or replace them yourself.

**NOTICE – Damage to the hammer**
When replacing the valve sleeve or valve housing, reusing the buffer can damage the hammer. Always replace the complete buffer 052-2707 as well.

**Variants and spare-parts orders**
FK 15.4: R 25 × 75; complete retaining cap 052-2520. Handle (8) is also available complete (052-2701). Two handle pins 304-3444.