
9 Exploded view FK 701

Schematic parts identification. Blue links open spare parts in the shop.



10 Spare parts

Item	Qty.	Description	Part number
1a	1	Bushing R 10.3 × 36	052-7233
1b	1	Bushing R 12.7 × 50	052-0043
1c	1	Bushing R 12.7 × 55	052-0083
2a	1	Cylinder	052-0012
2b	1	Cylinder	052-0082
3	1	Piston	052-0352
4	1	Lower cover	052-0051
5	1	Valve plate	307-2337
6	1	Upper cover	052-0050
7	1	Pin	304-5646
8	1	Buffer	307-2338
9	1	Complete handle	052-0151
10	1	Clamping nut	052-0058
11	1	Silencer	307-2540
12	1	O-ring	307-2439
13	1	Complete valve	052-0142
14	1	Strainer	304-5069
15	1	Trigger	307-2339
16	1	Compression spring	304-7015
17	1	Plug	306-0200
18	1	Valve bushing	052-0141
19	1	Hose without coupling	330-0160
20	1	Coupling	306-0805


NOTICE – Damage to the cylinder
Incorrect removal or replacement of the chisel bushing can damage the cylinder. Have chisel bushings replaced exclusively by F+K Service. Do not remove or replace them yourself.

NOTICE – Damage to the hammer
Reusing the old buffer when replacing the upper cover, lower cover or control plate can damage the hammer. Always replace buffer 307-2338 during this work.

Variants and spare-parts orders
The cylinders differ in their chisel-bushing socket. Cylinder 2a: only for bushing 1a (R 10.3 × 36). Cylinder 2b: for bushing 1b (R 12.7 × 50) or 1c (R 12.7 × 55). The bushings fit only the assigned cylinder. A also has regulator 052-0087. Hose 330-0160 replaces 052-0160; coupling 306-0805 separately. Handle (9) is also available complete (052-0151).

9 Exploded view FK 701A

Schematic parts identification. Blue links open spare parts in the shop.



10 Spare parts

Item	Qty.	Description	Part number
1a	1	Bushing R 10.3 × 36	052-7233
1b	1	Bushing R 12.7 × 50	052-0043
1c	1	Bushing R 12.7 × 55	052-0083
2a	1	Cylinder	052-0012
2b	1	Cylinder	052-0082
3	1	Piston	052-0352
4	1	Lower cover	052-0051
5	1	Valve plate	307-2337
6	1	Upper cover	052-0050
7	1	Pin	304-5646
8	1	Buffer	307-2338
9	1	Complete handle	052-0151
10	1	Clamping nut	052-0058
11	1	Silencer	307-2540
12	1	O-ring	307-2439
13	1	Complete valve	052-0142
14	1	Strainer	304-5069
15	1	Trigger	307-2339
16	1	Compression spring	304-7015
17	1	Plug	306-0200
18	1	Valve bushing	052-0141
19	1	Hose without coupling	330-0160
20	1	Coupling	306-0805
21	1	Regulator	052-0087

NOTICE – Damage to the cylinder
Incorrect removal or replacement of the chisel bushing can damage the cylinder. Have chisel bushings replaced exclusively by F+K Service. Do not remove or replace them yourself.

NOTICE – Damage to the hammer
Reusing the old buffer when replacing the upper cover, lower cover or control plate can damage the hammer. Always replace buffer 307-2338 during this work.

Variants and spare-parts orders
The cylinders differ in their chisel-bushing socket. Cylinder 2a: only for bushing 1a (R 10.3 × 36). Cylinder 2b: for bushing 1b (R 12.7 × 50) or 1c (R 12.7 × 55). The bushings fit only the assigned cylinder. A also has regulator 052-0087. Hose 330-0160 replaces 052-0160; coupling 306-0805 separately. Handle (9) is also available complete (052-0151).